

Portable /Fixed Appliance

Equipment formal visual and combined inspection and test



Part 1: Details of Installation

Client	James Baxter	Installation		Inspector Name	Gavin Brydon		
Address	7 Findhorn Place Edinburgh	Address	145/8 Bruntsfield Place Edinburgh	Branch No.	N/A	Scheme No.	20393
				Date of Test	14/10/2024	Date of Re-test	14/10/2025
				Test Equipment	UT-527		
				Signature	Gavin Brydon		
Postcode	EH9 2JR	Postcode	EH10 4EB				

Part 2: Test Results

Appliance No.	Description	Date of test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Earth Bond Ω	Insulation MΩ	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
1	Fridge freezer	14/10/2024	035	I	13	✓	>1	>299		✓		N/A		✓	Kitchen
2	Washer	14/10/2024	036	I	13	✓	>1	>299		✓		N/A		✓	Kitchen
3	Dishwasher	14/10/2024	037	I	13	✓	>1	>299		✓		N/A		✓	Kitchen
4	Fridge	14/10/2024	038	I	13	✓	>1	>299		✓		N/A		✓	Kitchen
5	Toaster	14/10/2024	039	I	13	✓	>1	>299		✓		N/A		✓	Kitchen
6	Kettle	14/10/2024	040	I	13	✓	>1	>299		✓		N/A		✓	Kitchen
7	Microwave	14/10/2024	041	I	13	✓	>1	>299		✓		N/A		✓	Kitchen

Test Result Totals:

Total Items Tested:	6	Total Failed Items Tested:	0
---------------------	---	----------------------------	---

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard) R11 - Repaired or refitted appliance case