

Portable /Fixed Appliance

Equipment formal visual and combined inspection and test

FT/PAT 5270000001557



Part 1: Details of Installation

Client	James Baxter	Installation	Inspector Name			Gavin Brydon		
Address	7 Findhorn Place Edinburgh	Address	151/7 Bruntsfield Place Edinburgh	Branch No.	N/A	Scheme No.	20393	
				Date of Test	14/10/2025	Date of Re-test	14/10/2026	
				Test Equipment	UT-527			
Postcode	EH9 2JR	Postcode	EH10 4EB	Signature	Gavin Brydon			

Part 2: Test Results

Appliance No.	Description	Date of test	Serial / Identification No.	Class I / II	Fuse size	Visual Only	Continuity/Earth Bond Ω	Polarity	Insulation M Ω	Load KW	Function Run	Earth leak mA	RCD Check	Repair Code	Pass / Fail	Location
1	Washer	14/10/2025	0001	I	13	✓	>1	N/A	>299		✓		N/A		✓	Kitchen
2	Dishwasher	14/10/2025	0002	I	13	✓	>1	N/A	>299		✓		N/A		✓	Kitchen
3	Toaster	14/10/2025	0003	I	13	✓	>1	N/A	>299		✓		N/A		✓	Kitchen
4	Kettle	14/10/2025	0004	I	13	✓	>1	N/A	>299		✓		N/A		✓	Kitchen
5	Fridge	14/10/2025	0005	I	13	✓	>1	N/A	>299		✓		N/A		✓	Kitchen
6	Microwave	14/10/2025	0006	I	13	✓	>1	N/A	>299		✓		N/A		✓	Kitchen
7	Fridge freezer	14/10/2025	0007	I	13	✓	>1	N/A	>299		✓		N/A		✓	Kitchen
8	Vacuum cleaner	14/10/2025	0008	II	13	✓		N/A	>299		✓		N/A		✓	Hall

Test Result Totals:

Total Items Tested: 8 Total Failed Items Tested: 0

Repair codes: 1 - Damaged flex – Re-terminated 2 - Damaged – Plug removed 3 - Safety fault R1 - Replaced plug top R2 - Replaced plug top fuse R3 - Change plug top fuse from 13A to 3A fuse R4 - Change plug top fuse from 13A to 5A fuse R5 - Change plug top fuse from 13A to 10A fuse R6 - Replaced extension lead R7 - Shortened damaged power-cord/cable and refitted plug top R8 - Rewired incorrectly wired plug top R9 - Repaired/refitted insecure or wrongly fitted power-cord/cable grip R10 - Removed cardboard wiring diagram from plug top (Fire hazard) R11 - Repaired or refitted appliance case