

Serial No
JB273095

Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500.

GD MILLS PLUMBING & HEATING LANDLORD/HOMEOWNER GAS SAFETY RECORD

This record can be used to document the outcomes of the checks and tests required by The Gas Safety (Installation and Use) Regulations. Some of the outcomes are as a result of visual inspection only and are recorded where appropriate. Unless specifically recorded no detailed inspection of the flue lining, construction or integrity has been performed.



Details of Registered Business

Gas Safe Register No **3951**
Registered Engineer's Name **RYAN MILLS**
Gas Safe Register Licence Number **4257470**
Business **GD MILLS PLUMBING & HEATING**
Address **11 HIGH STREET, LOANHEAD**
MIDLOTHIAN
Postcode **EH20 9RH**
Contact No **0131 440 0227**

Details of Site

Name (Mr/Mrs/Miss/Ms) **Kate Walker**
Address **4818 Bruntfield Place**
Postcode **EH10 4EB**
Contact No

Details of Customer/Landlord (or agent where appropriate)

Name (Mr/Mrs/Miss/Ms) **Mr James Boyle**
Address **7 Finnoch Place**
Edinburgh
Postcode **EH9 2DL**
Contact No

Number of Appliances tested

3

Appliance Details

	Location of	Type	Manufacturer	Model	Owned by Landlord/Homeowner Yes/No	Inspected Yes/No	Type of flue
1	KITCHEN	Boiler	VALLEY	EXCLUSIVE	YES	YES	BS
2	KITCHEN	HOB	-	-	YES	YES	OF
3	KITCHEN	HOB	-	-	YES	YES	OF
4							

Inspection Details

	Operating pressure in mbar and/or heat input kW/h or Btu/h	Operation of safety device(s)	Ventilation satisfactory	Visual condition of flue and termination	Flue operation checks	Combustion analyser reading (if applicable)	Appliance serviced	CO Alarm fitted	CO Alarm tested (if fitted)	SAFE TO USE
1	38.7444	PASS	YES	PASS	PASS	6.0008	YES	YES	PASS	YES
2	20.4	PASS	YES	NA	NA	0.0000	YES	YES	PASS	YES
3	20.4	PASS	YES	NA	NA	0.0000	YES	YES	PASS	YES
4										

Defects Identified

1	UNABLE TO GAIN ACCESS TO GAS METER	GLUSP classification eg. AR, ID	Warning/Advisory Record insert form serial No*
2			
3			
4			

Remedial Action Taken numbering should correspond to defects above.

1 Q10 BUENKA SEAL REPLACED.

Details of Work carried out

3.877~3/L
75
4.6
0.0008

* Refer to separate Warning/Advisory Record

select as appropriate and relevant

Outcome of gas installation pipework visual inspection?
Outcome of gas supply pipework visual inspection?
Is the Emergency Control Valve access satisfactory?
Outcome of gas tightness test?
Is the Protective Equipotential bonding satisfactory?

Pass / Fail / NA
Pass / Fail / NA
Pass / Fail / NA
Pass / Fail / NA
Pass / Fail / NA

Record issued by: Signature

Print Name

Received by: Signature

Date appliance(s)/flue(s) checked

ATTENTION

Next safety check due by:

20-10-19